

DISCLAIMER

The prices in our quotation are based on information given to CG Schmitt & Company Inc. / Moxie Surfaces at the time of the bid request. Verifying the specifications and quantity is your responsibility and you are made aware of the following and your customer should be made aware the following conditions and information.

1. Quote / Estimate may change for various reasons: sizes, quantities, specification changes, etc.
2. Quote/estimate is based on industry tolerances and accepted practices unless otherwise noted.
3. CG Schmitt & Company Inc. or Moxie Surfaces will make every effort to keep to our customer's scheduled delivery date, but will not be held liable for damages caused by delays, backlog and raw material delays or acts of god. We are not responsible for nor will we pay liquidated damages.
4. Special packaging and splitting shipments will be at customer's expense. Shipment must be inspected for freight damage upon receipt of order.
5. Shop drawings, engineering calculations or other design or engineering services are not included in the quote / estimate unless specifically stated otherwise.
6. The cost to CG Schmitt & Company Inc. to activate a lien will be billed to the customer.
7. Payment of local or state taxes are the sole responsibility of purchaser and not included in quotations.
8. Materials delivered and/or placed in storage, must be stored with protection from the weather, humidity and temperature variations (temperature of 60-85 degrees F and not more than 70 degrees relative humidity), dirt, dust, or other contaminants.
9. Installation of product constitutes acceptance of product.

RECEIPT OF PRODUCT PROCEDURES

1. Check the number of crates or cartons.
2. Check for correct address on freight bills, crates and/or cartons.
3. If there is damage on crates or cartons, or a shortage, you must have the truck driver make a damage or shortage report on all copies of freight bill at the time of delivery.
4. If you discover concealed damage, you must call freight carrier within 5 (five) working days and request an inspection of damaged freight. Document this inspection in writing with freight company and forward a copy of report to CG Schmitt & Company Inc. or Moxie Surfaces PO Box 231369 Encinitas CA 92023 760-230-4508 Fax (760) 452-7550.
5. Do not remove damaged crates or cartons from receiving area until after inspection has been completed. Save all packing, crating and cartons.
6. Do not return damaged goods unless authorized to do so. Freight will be refused at your cost.
7. DO NOT FILL OUT FREIGHT CLAIM UNLESS AUTHORIZED.
8. When you receive merchandise, check that your order is complete and correct. Check Quantity. INSTALLATION MEANS ACCEPTANCE OF MERCHANDISE.



Moxie Surfaces is the Strategic North American Partner and Distributor for design composite exterior and interior translucent polycarbonate panels.



www.moxiesurfaces.com